

Technical Bulletin Number 41

Ethernet Ports Usage

| To | | Product | |
|---------------------|--------------|-----------------------|------------|
| Company Name | All Partners | Part Number | DCP-2000 |
| Attention | | Description | |
| Phone | | Revision | 1.0 |
| Fax | | Effective Date | 07/03/2008 |
| Email | | | |

| | |
|--------------------|---|
| Description | <p>The ETH0 ethernet port is faster than the ETH1 ethernet port, both on old motherboard setup and on the current SE7221 motherboard.</p> <p>It is therefore recommended to use ETH0 for data transfer and to use ETH1 for the communication to the projector.</p> <p>By default ETH0 is configured as DHCP. However if there is no DHCP server, the initialization of ETH0 is going to fail and ETH1 will not be initialized either, leading to a failure to communicate with the any devices using ethernet.</p> <p>Configure the ETH0 with a fix IP if it is not connected or if there is no DHCP server on your network to ensure that ETH1 be always initialized properly.</p> |
|--------------------|---|

| | | | |
|-----------------------------|--|--------------|------------|
| Special Instructions | See document D2K.OM.000344.DRM – “DCP-2000 Field Installer Manual”, available on the Doremi Cinema web site, section “Support” - for the procedure to follow to change ETH0’s configuration. | | |
| Authorized by | Olivier Lambert | Date: | 07/03/2008 |
| Acknowledged by | | Date: | |